



Release Notes (October)

This release includes improved performance and bug fixes for [MaxiSys series products](#), and [MaxiSys 906/908/908 pro](#).

MaxiSys Series

✧ Europe:

◆ LandRover (V5.00)

Improvements:

➤ Added 405 special functions (including DPF, EPB, Steering, Battery, Seats, Headlamp, Throttle, Injector) for 8 models in 2016: New Range Rover, New Range Rover Sport, Range Rover Evoque, Range Rover Evoque Convertible, F-Type, New XF, XJ, XE.

◆ PSA (V5.11)

Bug fixes:

- Fixed bugs that caused errors in Configuration, BSI Key

Programming and After Sales Zone for 3008.

◆ **Renault/Dacia(V3.70)**

Improvements:

- Improved the way to enter system;
- Added 400 special functions, such as Injector Coding, Write

Saved Data/Save Saved Data, UCH Type/Speed Limiter.

✧ **Asia**

◆ **Subaru(V2.30)**

Improvements:

➤ Added 10 hot functions: Idle Speed Control (ISC), Fixed Idle Ignition Timing, Force Sensor Calibration Mode, Break-in Parking Brake Drive Mode, Parking Brake Removal Mode, Clutch Engagement Position Setting, Clutch Sensor Calibration Mode, Parameter Initialization Mode, Set mode Str.A.Sen.N&&Lat.GSen.Op and Oil Reset Without Tool.

◆ **Nissan/Infiniti (V5.20)**

Improvements:

➤ Added hot function menu for users to enter 15 hot functions (such as Injector, Brake and TPMS) through a fast path.

- Improved accuracy in fault code location, and updated Freeze Frame function for 26 systems.
- Developed a new mode for Anti-theft feature; updated the Coding function and added coverage for 7 ECUs.
- Added 203 functions, such as Save Computer Data, Write Saved Data and Oil Grade Factor.
- Added 50 Active Tests, such as Injector cylinder 1 and High pressure circuit leak test.
- Improved scanning time for system auto scan.
- Allows users to perform online anti-theft function without the 20-digit password for some models, such as 2013 TEANA, 2015 TEANA and 2015 X-trail.

Maxisys pro & 908 & 906

✧ American

◆ GMUSA(V9.70)

Bug fixes:

- Fixed an issue that caused inaccuracy in Read DTCs in ABS for 1999 Chevrolet Cavalier, and added Read DTCs in Instrument cluster system.

- Resolved an issue that caused failure in Read DTCs and VIN Analysis, and added Definitions for some fault codes in 2000 Buick Century.

- Fixed an issue where SIR and EBCM cannot be diagnosed in 2013 Chevrolet sail.

✧ **European:**

◆ **Opel/Vauxhall (V4.70)**

Improvements:

- Improved basic and special functions in Engine, Transmission, Chassis and Body for 2010, 2011, 2012 and 2014 Movano-B.

- Added Hot functions.

Bug fixes:

- Fixed bugs that caused problems in Auto Scan and Read DTCs in engine in 2012 Vivaro-PH3.

- Improved VIN Analysis function for 2016 models.

- Fixed an issue where DTCs are not identified in CIM for 2004 Vectra-C/Signum.

- Improved some translation in models display panel.

- Fixed an issue where ETC status bar displays error and Service function title is incorrect.

➤ Fixed bugs that caused functional problems in Active Test and special function Fuel Adjustment Reset in Fuel pump control module for 2013 Autara.

◆ **Benz (V8.12)(MaxiSys 908 pro only)**

Improvements:

- Added Steering Angle Calibration function in Chassis 163.
- Updated the version of ESP module in Chassis 253, 205, 222.
- Improved VIN Analysis function for models with Chassis

253.9XX.

- Updated model list and added some new models.

Bug fixes:

- Fixed an issue that caused incorrect definitions for fault codes.
- Resolved an issue that caused failure in Injector Quantity Adjustment in Chassis 203.

✧ **Asia**

◆ **Isuzu (V 3.10)**

Improvement:

- Updated and added coverage for TF/UC Series 2015 models.

Bug fixes:

➤ Fixed bugs that caused failure in VIN programming and Injector programming for 2008-2011 Colorado.

➤ Fixed bugs that caused failure in VIN programming and Injector programming for 2007-2014 TF/UC Series.

◆ **Isuzu (V2.50 Commercial vehicle)**

Improvements:

➤ Added coverage for 2016 Stripped Chassis(North America), N-Series(North America);

➤ Added support for Freeze Frame;

➤ Added support for special function Speedometer Calibration for H/C Series (North America) and F/T Series (North America) 6HK1 Diesel.

Bug fixes:

➤ Fixed bugs that caused errors when reading fault codes in engine control module for 2008, 2010, 2013 N-Series (North America) models with 4HK1 Diesel.

➤ Fixed bugs that caused failure in some VIN analysis.

◆ **Hyundai (V 6.40)(MaxiSys 908 only)**

Improvement:

➤ Added support for all basic functions for 2016-2017

Hyundai/Kia(general area), Beijing Hyundai, Dongfeng Yueda

Kia.