



Release Notes (December)

This release includes improved performance and bug fixes for [MaxiSys series products](#), and [MaxiSys 906/908/908 pro](#).

MaxiSys Series

✧ Europe:

◆ Ferrari (V2.10)

- Fixed communication problems in F1 Gearbox for some models.

◆ Renault/Dacia (V3.80)

- Added support for new models in 2016: CAPTUR/KAPTUR BR/IN/RU, SCENIC IV, KOLEOS II/QM6, KOLEOS II CN/QM6 CN, MEGANE IV SEDAN, ALASKAN;
- Added support for Renault Samsung series;

- Added 500 Hot Functions, such as DPF, Steering Wheel

Alignment and Rear View Camera Adjustment.

◆ **Fiat (V6.00)**

- Added 500 special functions.

✧ **Asia**

◆ **Subaru (V3.00)**

- Added support for VIN analysis and vehicle model selection;
- Improved fault codes library and data stream library;
- Improved program running and the response speed;
- Added support for basic functions and important special

functions for diesel engine;

- Added some special functions such as AT Learning Mode and AT Bleeding Mode.

✧ **American**

◆ **Ford (V 7.00)**

- Added support for Programmable Module Installation and Parameter Setting for models since 2008.

◆ **Chrysler (V8.00)**

- Added support for basic and special functions (except for online functions) on all 2017 vehicle models;

- Improved performance of all special functions for old models.

MaxiSys pro & 908 & 906

✧ **American**

◆ **GMUSA(V9.90)**

- Fixed an issue that caused function failure in Cooling Fan in Engine in TrailBlazer for 2007 Chevrolet Truck;
- Fixed an issue that caused failure in code clearing for some models of 2007 Chevrolet Captiva;
- Fixed problems in code reading in Engine for some models of 2015 Chevrolet Aveo and 2014 Chevrolet Sail;
- Fixed problems in code reading in Engine for 1997 GMC incomplete model.
- Fixed an issue that caused function failure in special function Program Key Fob for 2006 Chevrolet Corvette;
- Added Auto VIN Code Diagnosis for some models.

◆ **GM (V6.40)**

- Added Hot Function: Auto Reset;
- Fixed an issue that might cause communication failure in Active Test and Live Data for 2015 Chevrolet and Sail;

- Fixed an issue that might cause failure in Active Test, such as Pump Motor Test and Solenoid Valve Test, for 2004 Chevrolet and Sail;
- Fixed an issue that caused process problems in special function Steering Wheel Angle Sensor Centering in Power Steering Control Module for 2013 Chevrolet Cruze;
- Fixed problems in Auto Bleeding in ABS for 2006-2010 GL8 and Firstland, 2006-2008 WG LaCROSSE and WL LaCROSSE;
- Fixed bugs that caused error in Active Test and Live Data in Engine for 2005 GL8;
- Optimized the menu display for Active Test and special functions to improve user experience.

✧ **European:**

◆ **Opel/Vauxhall (V5.00)**

- Fixed bugs in special function Program Idle Speed under 2004/Corsa - C/Engine/Z 10 XEP;
- Fixed bugs in special function Regeneration D. Particulate Filter under 2011/Corsa-D/Engine/A 13 DTE;
- Fixed bugs in Read & Clear Code under 2002-2004/Vectra-C / Signum /Body/ CIM (Steering Column Module);

- Fixed bugs in special function DPF Service Regeneration under 2014/Vivaro (PH3)/ECM/Engine control module;

- Fixed bugs in special functions Program Immobilizer, Program Transponder-key, Program Immobilizer Output, Reset Immobilizer and Program Mechanical Key Number under 2001-2004/ Astra-G/ Immobilizer;

- Fixed bugs in special function Bleed Clutch Hydraulic under 2008/Corsa-D/TCM/MTA(Easytronic magneti marelli);

- Fixed bugs in special function Program Vehicle Identification No. under 2003/ Meriva/BCM;

- Added special function Program Special Vehicle under 2010-2014/Corsa-D/Engine/A 13 DTC.

◆ **Benz (V7.00)**

- Fixed an issue that the screen will return to model selection interface when perform Auto Scan;

- Fixed an issue that might cause function failure in Pressure Reservoir: Check Pretension Pressure in SBC system under Chassis 211.

- Fixed an issue that might cause failure in code clearing in SRS under Chassis 168;

- Improved VIN Code auto reading function;

➤ Fixed an issue that caused function failure in Calibration of control unit ABR in SBC system for Chassis 221;

➤ Fixed an issue that caused display error when reading fault codes during auto scanning in Transmission system under Chassis 251.

◆ **VW (V9.00)**

➤ Optimized model menu for VW, FAW-Audi, SVW, FAW-VW, Seat, Skoda, Lamborghini and VW Commercial vehicles;

➤ Added Guide function for brake pad replacement in EPB, and adds Auto Oil Reset function;

➤ Added some Hot Functions such as Transport Mode and Injector Adaption.

◆ **Benz (V7.00)(908 pro only)**

➤ Added diagnosis code guide function

◆ **Porsche (V6.00)(Maxisys908)**

➤ Improved all basic functions and Hot function Service Reset for models 911(977), Boxster 987 and Cayman 987;

➤ Added basic functions in DSN of Diesel engine for Old Cayenne.

✧ **Asia**

◆ **Isuzu (V3.31)**

- Fixed an issue that DTC status failed to be displayed in DTC

information interface for some systems.

- ◆ **Mitsubishi (V5.10) (MaxiSys 908 only)**

- Added support for Hot Function;
- Allows users to perform tests according to systems.

- ◆ **Hyundai(V6.51) (MaxiSys 908 only)**

- Optimized Smart Key Programming function and improved accuracy of the function;
- Optimized the menu of Hot Function and improved speed of response and accuracy.