



Release Notes (August)

This release contains improved performance and bug fixes for [MaxiSys series products](#), [MaxiSys 906/908/908 pro](#), [MaxiSys 908 Pro](#) and [MaxiSys 908](#).

MaxiSys Series

✧ American:

◆ Ford (V6.61)

- Fixed an issue that could cause failure in test for PATS function for some models.

MaxiSys 906/908/908 pro:

✧ American:

◆ GMUSA (V9.50)

- Added coverages for Chevrolet 2005-2013 Caprice/Lumina, systems can be diagnosed including ECM,ABS/TC/ESP 8.0,IPC,TCM,BCM,EBCM,SIR,Electronic Suspension Control,Fuel Injector Control Module,Fuel Pump Control Module,HVAC (Heating Ventilation and Cooling),AHL (Automatic Headlamp Levelling)Immobiliser,MSM (Memory Seat and Mirrors),Park Assist,RFA (Remote Function Actuator),RSE (Rear Seat Entertainment)
- Fixed an issue that could cause failure in special function “RFA Option Configuration” for 2004 Chevrolet Implala.
- Fixed an issue that could cause failure in special function “Idle Learn Reset” for 2008 Chevrolet Spark.
- Fixed an issue where special function “TPM Learn Mode” Hybrid could fail to display its status for 2010 Chevrolet Malibu.
- Improved the ability to analyze VIN codes of some models

✧ **European**

◆ **Opel/Vauxhall (4.60)**

- Supports diagnosis in 7 systems, including Add On Heater, Airbag, Body Control Module, CAN Interface Module, Engine Control Module, Park Piolt, Transmission Control Module for

2011-2014 Vivaro (PH3); and diagnosis in 4 systems, including ABS/ESP,K10B,K12B,TCM (Transmission Control Module) for 2008-2014 Agila-B.

- Fixed an issue that could cause failure in some special functions under Service Menu.
- Fixed an issue where displayed Live data is incorrect in Cylinder balance control when executing Engine Active test for 2007 Vectra-C / Signum Z19DTH.
- Added special function “Program Transponder-key” in Immobilizer system for 2000 Corsa-B.
- Added Read & Clear codes and Live data in Electronic Brake Control Module and Power Steering Control Module for 2015 Vivaro-B.

MaxiSys 908

✧ Asia:

◆ Subaru (V2.20)

Improvements:

- Added function menu “Hot function”, in which users can search and enter all hot functions.
- Fixed bugs that could cause failure in some special functions .
- Added diagnosis in "Parking brake System".

MaxiSys 908 pro

✧ European:

◆ Aston Martin (V1.00)

Improvements:

- Added Read codes, Clear codes, Live data and Active test for models of Aston Martin, including Cygnet (From 2011), DB9 (From 2004), DBS V12 (From 2007), Rapide (From 2009), Vantage (From 2005), Virage (From 2011).
- Added all Hot functions for supported models.

◆ BMW (V9.80.06)

Improvements:

- Fixed an issue where the screen interface jumped to Logo selection after programming data had been downloaded in Programming module.
- Fixed an issue where the screen interface jumped to Logo selection after obtaining invalid VIN.
- Fixed an issue where wrong part number is displayed after ECU replacement and installation.
- Fixed an issue where program crash is caused by abnormal data from ECU.

◆ Benz (V8.10)

Improvements:

- Added Driving authority learning in 8 ECUs for chassis 204.
- Added Coding function in 35 ECUs for chassis 212, 204.
- Added function “Enabling of engine start after crash event”
(only for engine MED40).
- Added icons for hot functions under the menu of Hot functions.

◆ Maserati (V2.01)

Improvements:

- Added **ECU information**, **Live data** and **Active test** for
QUATTROPORTE 2004-2006, QUATTROPORTE 2007-2009,
GranTurismo, Alfa Romeo 8C, COUPE' - SPYDER - GRANSPO
- GRANSPO SPYDER, 3200 GT, 3200 GT – EOBD, GHIBLI -
QUATTROPORTE OLD, QUATTROPORTE (M156), GHIBLI
(M157), GRANCABRIO - GRANTURISMO CONVERTIBLE.
- Added 800 special functions, including EPB calibration,
Service, Throttle adaption, TPMS programming and ABS
bleeding.